Oil Field Environmental Incident Summary

Responsible Party:MARATHON OIL COMPANYWell Operator:MARATHON OIL COMPANY

Well Name: JACK PENNINGTON 21-28H

Field Name: REUNION BAY Well File #: 16778

Date Incident:6/13/2015Time Incident:01:30Facility ID Number:County:MOUNTRAILTwp:151Rng:93Sec:28Qtr:

Location Description: On facility site in tank containment

Submitted By: Callie Karrigan Received By:

Contact Person: Paul Beacham

8902 37th St NW

New Town, ND 58763

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site				Reported to NRC: No		
	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	
Brine					0	
Other					0	

Description of Other Released Contaminant:

No released substance - the fiber glass tank was out of service and empty.

Inspected: Written Report Received: 6/18/2015 Clean Up Concluded: 6/13/2015

Risk Evaluation:

There was a potential for explosive atmosphere due to the fire and the vent line being damaged due to the lightning strike.

Areal Extent:

Potential Environmental Impacts:

There was no product in the fiber glass tank due to it being out of service. There was no impact to the soil. There was some foam that was sprayed onto a few spots of the tank that will need to be cleaned up.

Action Taken or Planned:

The well was shut-in and then locked and tagged out. The site will be evaluated during the next 48 hours due to the vent line being damaged and a producing tank having external damage. The fire was watched by the local fire department as well as a Marathon representative onsite. The fire self-extinguished although spray foam was applied due to the smoldering concern.

Wastes Disposal Location:

Agencies Involved: Local Fire Department, MHA, BIA

Updates

Date: 6/15/2015 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire on location. Nothing released off location according to the report. NDIC retains oversight.